current in the three-phase alternating current received by the three-phase UPS, an input voltage  $U_b$  of the B-phase alternating current in the three-phase alternating current received by the three-phase UPS, and an input voltage  $U_c$  of the C-phase alternating current in the three-phase alternating current received by the three-phase UPS, that is,  $V_0$ =( $U_a$ +  $U_b$ + $U_c$ )/3.

[0051] When the frequency of the 0-axis reference current is the 3Nth-order harmonic frequency of the mains, a phase of the 0-axis reference current, an amplitude of the 0-axis reference current, and a proportion during proportional adjustment on the difference between the 0-axis reference current and the 0-axis sampling current are adjusted, so that the 0-axis current forms a closed loop, that is, the 0-axis current forms a negative feedback, and when the zero wire of the three-phase uninterruptible power supply is normal, a location of a wave peak of each of the A-phase modulated wave, the B-phase modulated wave, and the C-phase modulated wave is the same as a location of a wave trough of the 0-axis reference current, and a location of a wave trough of the modulated wave is the same as a location of a wave peak of the 0-axis reference current. In this way, a wave peak of each of the A-phase modulated wave, the B-phase modulated wave, and the C-phase modulated wave that are obtained after the 0-axis reference current is superposed falls, and a wave trough of each of the A-phase modulated wave, the B-phase modulated wave, and the C-phase modulated wave that are obtained after the 0-axis reference current is superposed rises, avoiding that a wave peak of a modulated wave is higher than a wave peak of a carrier, and that a wave trough of a modulated wave is lower than a wave trough of a carrier.

[0052] Optionally, as shown in FIG. 5, the determining that a zero wire of a three-phase UPS is lost includes:

[0053] S501. Determine absolute values of average values of voltages of phases in the three-phase alternating current received by the three-phase UPS.

[0054]  $\overline{U_a}=\int_t^{t+T}U_a dt$  is an average value of voltages of the A-phase alternating current in the three-phase alternating current received by the three-phase UPS, where  $U_a$  is an instantaneous value of the voltage of the A-phase alternating current in the three-phase alternating current received by the three-phase UPS;  $\overline{U_b}=\int_t^{t+T}U_b dt$  is an average value of voltages of the B-phase alternating current in the three-phase alternating current received by the three-phase UPS, where  $U_b$  is an instantaneous value of the voltage of the B-phase alternating current received by the three-phase alternating current received by the three-phase alternating current

**[0055]**  $\overline{U_c}$ = $\int_t^{t+T} U_c dt$  an average value of voltages of the C-phase alternating current in the three-phase alternating current received by the three-phase UPS, where  $U_c$  is an instantaneous value of the voltage of the C-phase alternating current in the three-phase alternating current received by the three-phase UPS, and T is a mains cycle.

[0056] S502. When a smallest value of the absolute values of the average values of the voltages of the phases in the three-phase alternating current received by the three-phase UPS is greater than a first threshold, determine that the zero wire of the three-phase UPS is lost.

**[0057]** If  $\overline{U_{NGmin}}$ =min  $\{|\overline{U_a}|, |\overline{U_b}|, |\overline{U_c}|\}$ , when  $\overline{U_{NGmin}}$  is greater than the first threshold, it is determined that the zero wire of the three-phase UPS is lost.

[0058] Optionally, as shown in FIG. 6, the three-phase UPS control method provided in this embodiment of the present disclosure further includes:

[0059] S601. Determine that the zero wire of the three-phase UPS recovers, that is, a zero wire between an alternating current power network and a p point in FIG. 2 is connected.

[0060] S602. Use, as the 0-axis reference current, a signal obtained after proportional integral is performed on a difference between a bus difference reference voltage  $V_{NG\_ref}$  and an actual bus difference  $V_{NG}$ , where the bus difference reference voltage  $V_{NG\_ref}$  is zero, that is,  $V_{NG\_ref}$ 0; and then, generate the 0-axis modulated wave according to the difference between the 0-axis reference current and the 0-axis sampling current.

[0061] The actual bus difference is  $V_{busP}$ – $V_{busN}$ ,  $V_{busP}$  is a voltage on a positive bus capacitor, and  $V_{busN}$  is a voltage on a negative bus capacitor.

[0062] When the zero wire is connected, a valid value of a current on the zero wire is obviously relatively large; therefore, optionally, as shown in FIG. 7, the determining that the zero wire of the three-phase UPS recovers includes: [0063] S701. Determine a valid value of a current, on the zero wire, in the three-phase alternating current received by the three-phase UPS.

[0064] The valid value of the current, on the zero wire, in the three-phase alternating current received by the three-phase UPS is

$$I_{N\_RECrms} = \sqrt{\frac{1}{T} \int_t^{t+T} I_{N\_REC}^2 dt} \; , \label{eq:In_rec}$$

where  $I_{N\_REC}$  is an instantaneous value of the current, on the zero wire, in the three-phase alternating current received by the three-phase UPS,  $I_{N\_REC} = I_{LA} + I_{LE} + I_{LC}$ ,  $I_{LA}$  is an instantaneous value of the current on the rectifier inductor connected to the rectifier that rectifies the A-phase alternating current in the three-phase UPS,  $I_{LB}$  is an instantaneous value of the current on the rectifier inductor connected to the rectifier that rectifies the B-phase alternating current in the three-phase UPS and  $I_{LC}$  is an instantaneous value of the current on the rectifier inductor connected to the rectifier that rectifies the C-phase alternating current in the three-phase UPS

[0065] S702. When the valid value of the current, on the zero wire, in the three-phase alternating current received by the three-phase UPS is greater than a second threshold, determine that the zero wire of the three-phase UPS recovers.

[0066] An actual application of the three-phase UPS control method provided in this embodiment of the present disclosure is shown in FIG. 8, and FIG. 8 describes an example in which a rectifier in the three-phase UPS is controlled in a dq0 coordinate system. Bus voltage control is implemented on a d axis in the dq0 coordinate system, which includes: performing proportional adjustment on a difference between a bus reference voltage and a bus voltage to control the bus voltage, performing proportional integral on a difference between a d-axis reference current and a d-axis sampling current that are output after proportional adjustment, and determining a d-axis modulated wave according to a d-axis sampling voltage and a signal that is